

RESERVE STUDIES | INSURANCE APPRAISALS | WIND MITIGATION



Prepared Exclusively for Village on the Green Condominium III Association, Inc.

As of 4/5/2021 | FPAT File# MUD2115296



Felten Property Assessment Team

866.568.7853 | www.fpat.com

RECAPITULATION OF MITIGATION FEATURES For 2561 Royal Pines Cir, Units A-H

1. Building Code: Unknown or does not meet the requirements of Answer A or B

Comments: The year of construction was verified as 1979 per Pinellas County

Property Appraiser.

2. Roof Covering: FBC Equivalent

Comments: The roof covering was replaced in 2006. The roof permit was confirmed

and the permit number is BCP2006-09218. This roof was verified as meeting the building code requirements outlined on the mitigation

affidavit.

3. Roof Deck Attachment: Level A

Comments: Inspection verified 1/2" plywood roof deck attached with staples at a

minimum 6" on the edge & 12" in the field.

4. Roof to Wall Clips

Attachment:

Comments: Inspection verified embedded straps fastened with a minimum of three

nails.

5. Roof Geometry: Other Roof

Comments: Inspection verified a gable roof shape.

6. SWR: No

Comments: Inspection verified no secondary water resistance.

7. Opening Protection: None or Some Glazed Openings

Comments: Inspection verified no opening protection.

Address Verification



Exterior Elevation



Roof Construction



Roof Construction









Uniform Mitigation Verification Inspection Form

Maintain a copy of this form and any documentation provided with the insurance policy

intermediate of the form and any documentation provided with the insurance pointy					
Inspection Date: 4/5/2021					
Owner Information					
Owner Name: Village on the Green Condominium III		Contact Person: Robert Kelly			
Address: 2561 Royal Pines Cir, Units A-H		Home Phone:			
City: Clearwater	Zip: 33763	Work Phone: (727) 726-8000			
County: Pinellas		Cell Phone:			
Insurance Company:		Policy #:			
Year of Home: 1979	# of Stories: 2	Email: rkelly@ameritechmail.com			

NOTE: Any documentation used in v accompany this form. At least one ph though 7. The insurer may ask additional transfer of the control of th	otograph must acc	company this form	to validate each attribute m	arked in questions 3
 Building Code: Was the structure be the HVHZ (Miami-Dade or Broward A. Built in compliance with the FBC: 3/1/2002: Building Permit Applier. B. For the HVHZ Only: Built in comprovide a permit application with [X]. C. Unknown or does not meet the result. 	Year Built . For lacation Date (MM/DD/Appliance with the SF in a date after 9/1/19	lorida Building Cod nomes built in 2002/ YYYY) BC-94: Year Built _ 1994: Building Permi	e (SFBC-94)? 2003 provide a permit applica For homes built in 1	994, 1995, and 1996
2. Roof Covering: Select all roof cover OR Year of Original Installation/Reprovering identified.				mpliance for each roof
2.1 Roof Covering Type:	Permit Application Date	FBC or MDC Product Approval #	Year of Original Installation or Replacement	No Information Provided for Compliance
 [X] 1. Asphalt/Fiberglass Shingle [] 2. Concrete/Clay Tile [] 3. Metal [] 4. Built Up [] 5. Membrane [] 6. Other 	9/13/2006			0 0 0 0 0 0
 [X] A. All roof coverings listed above installation OR have a roofing permit application after 9/1/199 [] C. One or more roof coverings do not D. No roof coverings meet the requirement. 	permit application of Dade Product Appr 14 and before 3/1/20 t meet the requirem	date on or after 3/1/0 roval listing current a 002 OR the roof is onents of Answer "A"	OZ OR the roof is original and at time of installation OR (for original and built in 1997 or la	built in 2004 or later. the HVHZ only) a roofing
 3. Roof Deck Attachment: What is the [X] A. Plywood/Oriented strand board staples or 6d nails spaced at 6" al -OR- Any system of screws, na uplift less than that required for [] B. Plywood/OSB roof sheathing with 24" inches o.c.) by 8d common roother deck fastening system or transminum of 12 inches in the fide. [] C. Plywood/OSB roof sheathing with the proof of the proof of	(OSB) roof sheathi ong the edge and 12 ils, adhesives, othe Options B or C belo ith a minimum thic nails spaced a maxin uss/rafter spacing the el or has a mean up	ng attached to the ro 2" in the fieldOR-1 or deck fastening system. ekness of 7/16" inch mum of 12" inches that is shown to have blift resistance of at	sof truss/rafter (spaced a maxibatten decking supporting wookstem or truss/rafter spacing that attached to the roof truss/raftin the fieldOR- Any system an equivalent or greater resistlesst 103 psf.	od shakes or wood shingles, nat has an equivalent mean eter (spaced a maximum of of screws, nails, adhesives, tance than 8d nails spaced a
24"inches o.c.) by 8d common r				

Inspectors Initials Property Address 2561 Royal Pines Cir, Units A-H, Clearwater

decking with a minimum of 2 nails per board (or 1 nail per board if each board is equal to or less than 6 inches in width). -OR-Any system of screws, nails, adhesives, other deck fastening system or truss/rafter spacing that is shown to have an equivalent

^{*}This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.

or great 182 psf.	er resistance than 8d common nails spaced a maximum of 6 inches in the field or has a mean uplift resistance of at least
	d Concrete Roof Deck.
E. Other:	
[] F. Unknown [] G. No attic a	
5 feet of the	<u>I Attachment</u> : What is the <u>WEAKEST</u> roof to wall connection? (Do not include attachment of hip/valley jacks within inside or outside corner of the roof in determination of WEAKEST type)
[] A. Toe Nails	[] Truss/rafter anchored to top plate of wall using nails driven at an angle through the truss/rafter and attached to the top plate of the wall, or
	[] Metal connectors that do not meet the minimal conditions or requirements of B, C, or D
Minimal cor	nditions to qualify for categories B, C, or D. All visible metal connectors are:
	[X]Secured to truss/rafter with a minimum of three (3) nails, and [X]Attached to the wall top plate of the wall framing, or embedded in the bond beam, with less than a ½" gap from the blocking or truss/rafter and blocked no more than 1.5" of the truss/rafter, and free of visible severe
[X] B. Clips	corrosion.
, , ,	[X] Metal connectors that do not wrap over the top of the truss/rafter, or [] Metal connectors with a minimum of 1 strap that wraps over the top of the truss/rafter and does not meet the nail position requirements of C or D, but is secured with a minimum of 3 nails.
[] C. Single Wr	raps
	Metal connectors consisting of a single strap that wraps over the top of the truss/rafter and is secured with a minimum of 2 nails on the front side and a minimum of 1 nail on the opposing side.
[] D. Double W	
	[] Metal Connectors consisting of 2 separate straps that are attached to the wall frame, or embedded in the bond beam, on either side of the truss/rafter where each strap wraps over the top of the truss/rafter and is secured with a minimum of 2 nails on the front side, and a minimum of 1 nail on the opposing side, or [] Metal connectors consisting of a single strap that wraps over the top of the truss/rafter, is secured to the wall on both sides, and is secured to the top plate with a minimum of three nails on each side.
[] E. Structural	Anchor bolts structurally connected or reinforced concrete roof.
[] G. Unknown [] H. No attic a	
	etry: What is the roof shape? (Do not consider roofs of porches or carports that are attached only to the fascia or wall of eture over unenclosed space in the determination of roof perimeter or roof area for roof geometry classification).
[] A. Hip Roof	Hip roof with no other roof shapes greater than 10% of the total roof system perimeter. Total length of non-hip features: ; Total roof system perimeter:
[] B. Flat Roof	
[X] C. Other R	
[] A. SWR (als sheathing from w [X] B. No SWI	Water Resistance (SWR): (standard underlayments or hot-mopped felts do not qualify as an SWR) o called Sealed Roof Deck) Self-adhering polymer modified-bitumen roofing underlayment applied directly to the ng or foam adhesive SWR barrier (not foamed-on insulation) applied as a supplemental means to protect the dwelling atter intrusion in the event of roof covering loss. R. or undetermined.

Inspectors Initials Property Address 2561 Royal Pines Cir, Units A-H, Clearwater

7. Opening Protection: What is the weakest form of wind borne debris protection installed on the structure? First, use the table to determine the weakest form of protection for each category of opening. Second, (a) check one answer below (A, B, C, N, or X) based upon the lowest protection level for ALL Glazed openings and (b) check the protection level for all Non-Glazed openings (.1, .2, or .3) as applicable.

Opening Protection Level Chart Place an "X" in each row to identify all forms of protection in use for each opening type. Check only one answer below (A thru X), based on the weakest form of protection (lowest row) for any of the Glazed openings and indicate the weakest form of protection (lowest row) for Non-Glazed openings.		Glazed Openings				Non-Glazed Openings	
		Windows or Entry Doors	Garage Doors	Skylights	Glass Block	Entry Doors	Garage Doors
N/A	Not Applicable- there are no openings of this type on the structure						
Α	Verified cyclic pressure & large missile (9-lb for windows doors/4.5 lb for skylights)						
В	Verified cyclic pressure & large missile (4-8 lb for windows doors/2 lb for skylights)						
С	Verified plywood/OSB meeting Table 1609.1.2 of the FBC 2007						
D	Verified Non-Glazed Entry or Garage doors indicating compliance with ASTM E 330, ANSI/DASMA 108, or PA/TAS 202 for wind pressure resistance						
N	Opening Protection products that appear to be A or B but are not verified						
IN	Other protective coverings that cannot be identified as A, B, or C						
х	No Windborne Debris Protection						

- [] A. Exterior Openings Cyclic Pressure and 9-lb Large Missile (4.5 lb for skylights only) All Glazed openings are protected at a minimum, with impact resistant coverings or products listed as wind borne debris protection devices in the product approval system of the State of Florida or Miami-Dade County and meet the requirements of one of the following for "Cyclic Pressure and Large Missile Impact" (Level A in the table above).
 - Miami-Dade County PA 201, 202, and 203
 - Florida Building Code Testing Application Standard (TAS) 201, 202, and 203
 - American Society for Testing and Materials (ASTM) E 1886 and ASTM E 1996
 - Southern Standards Technical Document (SSTD) 12

 For Skylights Only: ASTM E 1886 <u>and</u> ASTM E 1996
 For Garage Doors Only: ANSI/DASMA 115
☐ A.1 All Non-Glazed openings classified as A in the table above, or no Non-Glazed openings exist
☐ A.2 One or More Non-Glazed openings classified as Level D in the table above, and no Non-Glazed openings classified as Level B, C, N, or X in the table above
☐ A.3 One or More Non-Glazed Openings is classified as Level B, C, N, or X in the table above
[] B. Exterior Opening Protection- Cyclic Pressure and 4 to 8-lb Large Missile (2-4.5 lb for skylights only) All Glazed openings are protected, at a minimum, with impact resistant coverings or products listed as windborne debris protection devices in the product approval system of the State of Florida or Miami-Dade County and meet the requirements of one of the following for "Cyclic Pressure and Large Missile Impact" (Level B in the table above):
• ASTM E 1886 <u>and</u> ASTM E 1996 (Large Missile – 4.5 lb.)
• SSTD 12 (Large Missile – 4 lb. to 8 lb.)
• For Skylights Only: ASTM E 1886 and ASTM E 1996 (Large Missile - 2 to 4.5 lb.)
☐ B.1 All Non-Glazed openings classified as A or B in the table above, or no Non-Glazed openings exist
☐ B.2 One or More Non-Glazed openings classified as Level D in the table above, and no Non-Glazed openings classified as Level C, N, or X in the table above
☐ B.3 One or More Non-Glazed openings is classified as Level C, N, or X in the table above
[] <u>C. Exterior Opening Protection- Wood Structural Panels meeting FBC 2007</u> All Glazed openings are covered with plywood/OSB meeting the requirements of Table 1609.1.2 of the FBC 2007 (Level C in the table above).
☐ C.1 All Non-Glazed openings classified as A, B, or C in the table above, or no Non-Glazed openings exist

☐ C.2 One or More Non-Glazed openings classified as Level D in the table above, and no Non-Glazed openings classified as Level N or X in

Inspectors Initials Property Address 2561 Royal Pines Cir, Units A-H, Clearwater

☐ C.3 One or More Non-Glazed openings is classified as Level N or X in the table above

the table above

^{*}This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.

	_				
FPAT	File	#MII	M21	15296	

[] N. Exterior Opening Protection (unverified shutter syst protective coverings not meeting the requirements of "B" with no documentation of compliance (Level N is	Answer "A", "B", or C" or				
☐ N.1 All Non-Glazed openings classified as Level A, B, C, or	N in the table above, or no No	on-Glazed openings exist			
☐ N.2 One or More Non-Glazed openings classified as Level E table above	in the table above, and no No	n-Glazed openings classified as Level X in the			
☐ N.3 One or More Non-Glazed openings is classified as Level	X in the table above				
$[X] \ \underline{\textbf{X. None or Some Glazed Openings}} \ One or more Glazed of the property of the pr$	openings classified and Lev	el X in the table above.			
MITIGATION INSPECTIONS MUST B Section 627.711(2), Florida Statutes, provi					
Qualified Inspector Name: John Felten	License Type: CBC	License or Certificate #: CBC1255984			
Inspection Company: Felten Property Assessment Team		Phone: 866-568-7853			
Qualified Inspector – I hold an active license as a:	(check one)				
Home inspector licensed under Section 468.8314, Florida Statutes training approved by the Construction Industry Licensing Board a					
 □ Building code inspector certified under Section 468.607, Florida S □ General, building or residential contractor licensed under Section 					
$\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ $	tutes.				
☐ Professional architect licensed under Section 481.213, Florida Sta					
Any other individual or entity recognized by the insurer as posses verification form pursuant to Section 627.711(2), Florida Statutes		ns to properly complete a uniform mitigation			
Individuals other than licensed contractors licensed under Sunder Section 471.015, Florida Statues, must inspect the structure sees under s.471.015 or s.489.111 may authorize a direct experience to conduct a mitigation verification inspection.	uctures personally and no	t through employees or other persons.			
I, <u>John Felten</u> am a qualified inspector and I contractors and professional engineers only) I had my employand I agree to be responsible for his/her work.					
Qualified Inspector Signature: Date: 4/5/2021					
Quanticu inspector Signature.	<u>+/ 5/ 2021</u>				
An individual or entity who knowingly or through gross negligence provides a false or fraudulent mitigation verification form is subject to investigation by the Florida Division of Insurance Fraud and may be subject to administrative action by the					
appropriate licensing agency or to criminal prosecution. (Se certifies this form shall be directly liable for the misconduct performed the inspection.					
<u>Homeowner to complete</u> : I certify that the named Qualified residence identified on this form and that proof of identification					
Signature:D	ate:				
An individual or entity who knowingly provides or utters a false or fraudulent mitigation verification form with the intent to obtain or receive a discount on an insurance premium to which the individual or entity is not entitled commits a misdemeanor of the first degree. (Section 627.711(7), Florida Statutes)					

The definitions on this form are for inspection purposes only and cannot be used to certify any product or construction feature as offering protection from hurricanes.

Inspectors Initials Property Address 2561 Royal Pines Cir, Units A-H, Clearwater

OIR-B1-1802 (Rev. 01/12) Adopted by Rule 69O-170.0155

^{*}This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.